



JPS Reliability

A Reliable Plant is a Profitable Plant

Bonus - Case Study #6

Dynamic Vibration Absorber

Distributing energy in line with the First Law of Thermodynamics

PROfessional services for **PRO**active maintenance

CASE STUDIES

The integration of the **MIRCE Science Theory** and **JPS Reliability Reality** is illustrated through the following 6 case studies:

1. Electrical Motor Terminal Connection Defect
 2. Standby Fan Motor Defect
 3. Variable Frequency Drive Deterioration
 4. Vibrating Screen Gearbox Bearing Defect
 5. 4 Point Contact Bearing 23RPM Defect
 6. **Dynamic Vibration Absorber**
- Each slide we will discuss how the defect was detected and what actions were/were not put in place to protect the functionality of the system



HISTORY & BACKGROUND



- High lift pumps at the pumping station facility have historically suffered from low reliability and required many expensive overhauls with new bearing sets (Babbitt/White Metal)
- Various attempts to resolve the root cause have not been successful



BEARING LOCATION

Tilting pad bearing location



Bed Plate – view from underneath






BEARING INSPECTION: OIL

- Microscopic inspection of the oil, debris is present





BEARING INSPECTION: TILTING PAD

- The pads vary from no contact to full contact and cracking of the tilting pad, indicating eccentric (non-orbital) motion




BEARING INSPECTION: TILTING PAD

- Microscopic image of a pad with no wiping, and an image of a pad with wiping damage





BEARING INSPECTION:TILTING PAD

- Microscopic image of the cracked pad surface displaying fatigue cracking



BEARING INSPECTION: TILTING PAD


- Microscopic cross sectional image of the cracked pad
- Bond line intact
- Failure is at the weakest point, the pivot point





JPS Reliability
A Reliable Plant is a Profitable Plant

VIBRATION ANALYSIS






VELOCITY SPECTRA

- Forcing function 1 Order
- Directional vibration
- Vibration changes with speed

Dial Number	RPM	1 Order	Overall
0	662.51	30.25	35
1	679.34	26.94	28.96
2	694.75	20.98	21.22
3	707.68	15.87	18.00
4	721.29	12.77	15.02
5	740.79	11.63	13.69



ADDING MASS TO THE SYSTEM


- The addition of weight moved the resonant frequency down to speed range 2
- The weight (additional mass 10Kg) dampened the vibration motion and lowered the resonant frequencies
- Conformation of a resonant condition





OVERALL VIBRATION VS SPEED: MASS ADDED



- The peak vibration is now occurring at speed set point 2
- As the speed increases the vibration reduces
- This type of vibration and speed relationship indicates a resonant issue





VIBRATION VS SPEED: STRIP CHART


- Speed 3 high fluctuation, indicating a critical speed / resonance / beat frequency
- Speed 5 lower levels and more constant




ORBIT DATA

Units=mm/sec
 X Diff = 22.73
 Y Diff = 22.50
 LOAD = 100.0
 704.50 Rpm

Units=mm/sec
 Filter=1xBP
 X Diff = 18.31
 Y Diff = 17.07
 LOAD = 100.0
 704.50 Rpm



Raw Data




1 Order Filtered





RESONANCE TEST 'BUMP TEST'

- Bump test indicating a structural resonance





FLOOR STRUCTURE



WORKSHOP: AMPLITUDE AND PHASE


- One order tracked
- Set up on a test bed no load
- Accelerometer location on the top of the motor (NDE)





ON-SITE: AMPLITUDE AND PHASE

- One Order tracked
- Set up on foundation under normal operational load
- Note how the structure changes the motion






WHY?

- Motor bearing failures, concentrated at the motor drive end





THE 'FIVE WHYS'







CONCLUSION

- There are no issues with the motor rebuild, the balance and dynamics of the motor when operated unloaded in the test bay, $>4\text{mm/s}$ RMS
- A structural resonance on site is causing an amplification of vibration levels
- This resonance increases the dynamic loads on the drive end bearing
- This then causes Babbitt fatigue, cracking, and Babbitt wiping due to rotor to stator contact

SUPPORT STEEL WORK: MODIFICATION



- A decision to stiffen the structure was made
- All good in theory but where does the energy go?



SUPPORT STEEL WORK: VIBRATION RESULTS

- Stiffening the structure increased the vibration levels to **35mm/s RMS**

Still high directional motion





JPS Reliability

A Reliable Plant is a Profitable Plant

DYNAMIC VIBRATION ABSORBER







WHAT IS A DVA?

- It is a tuned spring mass system which reduces or eliminates the vibration of a harmonically excited system
- All rotating machines can induce vibration due to structural resonances. A dynamic absorber can be tuned to excite in such a way exactly counteracts the force from the structural resonance
- Properly implemented, a dynamic absorber will neutralise the undesirable vibration, which would otherwise reduce service life or cause mechanical damage
- Dynamic absorbers differ from tuned mass dampers in that dynamic absorbers do not require any damping to function satisfactorily

DVA DESIGN: DUNKERLY METHOD



- Bar Cross Section
- Length
- Free Distance to weight
- Bar diameter
- Bar width
- Bar height
- Density
- Young's Modulus
- Target resonant frequency



DVA SITE INSTALLATION



Safety
tethers



DVA SITE INSTALLATION: VIDEO

- Normal Speed




DVA SITE INSTALLATION:VIDEO

- Slow Speed showing the point of flex



VIBRATION RESULTS: OVERALL LEVELS



Location	Radial (Deg.)	Normal Operational	Structural Mods	DVA
NDE (TOP)	0	10.86	35	5.41
	90	8.21	18.17	5.82
DE (BOTTOM)	0	2.41	9.55	1.27
	90	2.11	5.92	1.57



VIBRATION RESULTS: OVERALL WITH SPEED




TABLE OF DIRECTIONAL RATIO VIBRATION DATA


- This table is the difference in the radial vibration velocity in mm/s RMS (Lower the number the less stress to the bearings)

Location	Normal Operational	Structural Modifications	Vibration Dynamic Absorber
NDE (TOP)	2.65	16.83	0.41
DE (BOTTOM)	0.30	3.63	0.30



12 MONTH INSPECTION

- Follow Up



12 MONTH FOLLOW UP ON TRIAL


- The fatigue rate for the main arms of the Dynamic Vibration Absorbers are 11/12 months





INSTALLATION OF REPLACEMENT DVA ARMS

- One order vibration reduced from 13.7 to 4.5 mm/s RMS after the DVA Arms were replaced





DVA: SUMMARY

- The Dynamic Vibration Absorbers have been successful in absorbing the vibration energy from this asset ensuring low vibration levels and correct dynamic motion
- This will enable the asset to run longer in operation before maintenance/repair increasing the functionality of the pump and reducing the overall operational life costs of the asset
- The average costs to change the motor bearings is £15,000, if the motor failed the average cost for a full overhaul and rotor rewind is £55,000. This excludes the costs of loss of production and associated financial and reputation costs.



JPS Reliability

A Reliable Plant is a Profitable Plant

HOW WE CAN HELP



When a business requires support with or development of Health Based Maintenance we work in partnership in;

Upskill your team with Practical Mentoring in

- Ultrasound Airborne and Structural Borne
- Infrared Thermography-Low Voltage, Mechanical and Process
- Vibration Analysis
- General Maintenance Practices
- Practical Reliability Engineering

Contracted Reliability Services

- Contemporary Condition Monitoring consultancy to assist clients with the management of their Health Based Maintenance program



TECHNOLOGIES AND SERVICES

Vibration Analysis

- Unbalance
- Looseness
- Resonance
- Pump issues
- Gear faults/wear
- Inadequate lubrication
- Bearings
- Steam traps/valves

Lubrication

- Gear faults/wear
- Wrong oil/mixed
- Oil degradation
- Contamination
- Fuel dilution
- Leaking seals
- Bearings
- Overheating

Thermography

- Bearings
- Overheating
- Steam traps/valves
- Flammable gas leaks
- HV issues
- Electrical wiring faults
- Heat exchanger blockage
- Refractory applications

Ultrasound

- Inadequate lubrication
- Steam traps/valves
- Bearings
- Flammable gas / air leaks
- HV issues
- Corona discharge arcing
- Heat exchanger tubes/plate



JPS Reliability
A Reliable Plant is a Profitable Plant

CONTACT JPS RELIABILITY



info@jpsreliability.com



<https://jpsreliability.com>



07387 986 454

JPS Reliability LTD is a Company registered in England under company number 12547245. Bristol, UK.